.5/30

DART AEROSPACE LTD	Work Order:	23729
	Part Number:	D3137-3
Description: Guide		(p B30-23000-207)
FF 03.10.09 & C1 04,02.19 19		
Drawing: D3137 Rev. ATB PAGE 3 D	Qty:	20

		14106 3 3	wiy.					
مىدم	03.04.21 Rt 83.02.03 2F04.11.29							
Step	Location	Procedure		Ву	Date	Qty		
1	EXPEDITING	Issue Work Order		M	10			
	TH 04.04.27	Dwg not required		170	05,07,04	20		
2	METAL /	Cut Blanks.						
	CNC-CELL	Blank size: 1.250" x .750" x .9	50" long					
		Matl: Delrin bar (ref DART spe-	c. M-DELRIN-B)					
				36	05.080	70		
3	HAAS	Machine as per Folio FA242	Batch M 14535	1				
				\2V	3608,04	30		
4	QC	Inspect Level 2						
				12	40.60.20	20		
5	QC	Inspect Level 8			, ,			
				my	000864	20		
6	METAL /	Deburr break all unmarked sha	rp edges .005 to 0.010					
	CNC-CELL			121	10.00.20	20		
7	QC	Inspect Level 5			11			
			•	Int.	05/08/04	26		
8	STORES	Identify and stock			ł	1 *		
				1/1	5.84	なし		
9	EXPEDITING	Close W/O		10	†			
ļ		Inspect level 21	, ,					
		Cost/part 7,5/ 546 0	5/08/09 (20)	4	05/09/57	20		
		16,37						

Rev	Date	Change	Revised By	Approved
Α	02.05.29	New Issue		1202-05-29

RELEASED
02/05/29

Dart Aerospace Ltd

	WORK ORDER C	WORK ORDER CHANGES									
STEP	PROCEDURE CHANGE	Ву	By Date		Approval Mfg / Design Mgr	Approval QC Inspector					
	i					STEP PROCEDURE CHANGE By Date Qty Mfg / Design					

NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B	***************************************	Verification		Annessal		
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	Section C	Approval Design Mgr	Approval QC Inspector		
		,								
							<u></u>			
										
				·		'		{		
						<u></u>	L	L		

Part No:	PAR #:	Fault Category: NCR:	Yes	No DQA:	Date: <u>05</u> / ටලි	51
NOTE: Date & initial all entries			QA	: N/C Closed:	Date:	ś

DART AEROSPACE LTD	Work Order:	23729
Description: Guide	Part Number:	D3137-3
Inspection Dwg: D3137 Rev: D		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

Х	First Article	Prototype
	· ·	

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.175	+/-0.010	174/179		·		
Ø0.257	+0.005/-0.000	. 257				
Ø0.65 x 100°	+/-0.030	.650				
0.425	+/-0.010	いても	_			
0.550	+/-0.010	.550	_			
1.100	+/-0.010	1.100	<u> </u>			
0.470	+/-0.010	:474	_			
0.850	+/-0.010	. 452				
0.143	+/-0.010	.150				
				·		
	·					
					-	
				:		

Measured by: 36	Audited by:	and	Prototype Approval:	N/A
Date: 05.08.03	Date:	05/08/03	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	03.11.27	New Issue	KJ/RF	2//
В	04.11.12	0.175 was 0.145 & Ø0.65 x 100° was Ø0.75 x 100°	KJ/JLM	
				7



Job Costing Report

Dart Aerospace Ltd. Hawkesbury

Jun 30, 2005 02:06 pm

Work Order No : 0023729

Project Name : D3137-3 Project For : WK530

Work Order Type : Main

Main WO Number :

House Part Number: D3137-3

Description : Guide

Manufactured : Yes Amount Req'd :

Amount Done : 0

Start Date : 06-30-05 Est Finish Date : 07-30-05

20

Act Finish Date :

Drawings Reqd : No Ok for Approval :

Approval Rec'd :

Department Code:

Burden Flags : NNNNNN

WO Status : Open

Invoice State : Not Invoiced

Invoice Date :

Invoice Number:

Invoice Amount: 0.00

Order Entry No :

OE Value : 0.00

Est Mark Up : 0.000% Actual Mark Up : 0.000%


\$0 Posted to Finished Goods

		Estimated	Actual	Var. %	Posted	To Post
	==	========	=========	=======	========	=======================================
Material Cost	:	0.00	0.00	0.00	0.00	0.00
Engineering Hours	:	0.00	0.00	0.00		
Engineering Cost	:	0.00	0.00	0.00	0.00	0.00
Production Hours	:	0.00	0.00	0.00		
Production Cost	:	0.00	0.00	0.00	0.00	0.00
Packaging Hours	:	0.00	0.00	0.00		
Packaging Cost	:	0.00	0.00	0.00	0.00	0.00
OverHead Hours	:	0.00	0.00	0.00		
OverHead Cost	:	0.00	0.00	0.00	0.00	0.00
CNC Hours	:	0.00	0.00	0.00		
CNC	:	0.00	0.00	0.00	0.00	0.00
Misc. Hours	:	0.00	0.00	0.00		
Misc.	:	0.00	0.00	0.00	0.00	.0.00
		========	=======	======		
Burden	:	0.00	0.00	0.00		
		=======	========	=======		
Total Cost	:	0.00	0.00	0.00		
Mark up	:	0.000	0.000			
Selling Cost	:	0.00	0.00			


		Estimated	Actual
Labour Hrs/Amount Done	:	0.00	0.00
Profits/(Loss)	:	0.00	0.00



DESIGN	DRAWN BY		OSPACE LTD ONTARIO, CANADA	
CHECKED M	APPROVED	DRAWING NO.	REV. D	
#	H	D3137	SHEET 3 OF 4	
DATE .		TITLE	SCALE	
04.11.03		BRACKET ASSEMBLY	1:1	



- D3137-3 GUIDE
- 1) REPLACES PREMIER P/N B30-23000-207
- 2) MATERIAL: DELRIN BAR (REF DART SPEC. M-DELRIN-B)
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL EDGES 0.005 TO 0.015



D3137-5 WASHER

- 1) REPLACES PREMIER P/N B30-23000-209
- 2) MATERIAL: 6061-T6 (QQ-A-225/8 OR QQ-A-200/8) BAR (REF DART SPEC. M6061T6R)
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) ALL DIMENSIONS ARE IN INCHES
- 6) BREAK ALL EDGES 0.005 TO 0.015

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.